	Tombstone Diesel 599 Topeka Way STE 200 Castle Rock, CO 80109 Tel: 7203898569 travis@tombstonediesel.com				Servi	mate Q( ice Advisor: N Technician: ate: 02-19-20	lick Ganem Travis Kurz			
Customer	Nick Ondich (OND001)					C    40	0.010.7702			
	CO					Cell: 40	8-910-7703			
					n	icksapple06@	) gmail.com			
Vehicle	2015 Chevrolet Silverado 2500 HD WT 6.6 DIESEL 1GC1KWE82FF589882 1000					Miles In Miles Out License Pla				
Customer Issues and Advisories	Symptoms and Diagnostic Trouble Codes Customer requested a quote for a transmission & what supported mods are needed for 500whp Work Description Perform component list.									
Work to be Performed	Advisory Notes All card fees obtained are processed by NEWT 3% charge per card vendor and are not negoti receipt. This is an email estimate that is subject to cha present. All further concerns will then be docu Full parts deposit required prior to repair start Please review us on google and follow us on I Labor	able. Card fee amount winnight further concerns ar mented and discussed wind the discusse	ill be display re found witl ith customer	ed to cu n vehicle prior to	ustomer o e when tii o further i	on final proce me of service repairs.	essed			
	Labor BD Torque Master Transmission W/Fleece Cooler Lines			Hrs .00	Price 198.00		Total 0.00			
	<b>Parts</b> BD Torque Master	Part No AAATRQMSTR		Qty .00 7	<b>Price</b> ,637.07		<b>Total</b> 7,637.07			
	Freight	AAAFRGHT	1	.00	750.00		750.00			
	Schaeffer's full synthetic automatic transmission fluid	AT4ATF+4	25	.00	17.40		435.00			
	Fleece Transmission Cooler Lines	AAAFLCTRNCL	1	.00	471.41		471.41			
					Labor	SubTotal	\$9,293.48			
	Labor									
	<b>Labor</b> Fass Fuel System W/ Sump & 10mm CP3 Conversion			Hrs .00	Price 198.00		Total 0.00			
	Parts CP3 Conversion 10MM	Part No AAASSCPCNVR		<b>Qty</b> .00 3	<b>Price</b> ,995.05		<b>Total</b> 3,995.05			
					Labor	SubTotal	\$3,995.05			
							Page 1 of 2			

## Labor

	<b>Labor</b> Fleece Cheetah Turbo		Tech	Hrs 25.00	Price 198.00		Total 4,950.00
	<b>Parts</b> Fleece Cheetah	Part No AAAFLCCH		<b>Qty</b> 1.00	Price 3,784.29		Total 3,784.29
	Misc Gasket Kit	AAAMISCGSKT		1.00	250.00		250.00
	Hot Side Intercooler Pipe	AAAHTSDCLP		1.00	480.00		480.00
	Cold Side Intercooler Pipe	AAACLDP		1.00	480.00		480.00
					Labor	SubTotal	\$9,944.29
	Labor						
	<b>Labor</b> Radio Upgrade Kit		Tech	Hrs 0.00	Price 198.00		Total 0.00
	<b>Parts</b> Radio Upgrade Kit	Part No AAARDUPG		<b>Qty</b> 1.00	Price 1,500.00		Total 1,500.00
					Labor	SubTotal	\$1,500.00
	Labor						
	<b>Labor</b> Diagnose and Advise		Tech	Hrs 1.00	Price 198.00		Total 198.00
					Labor	SubTotal	\$198.00
Total						Labor Parts Hazmat* Supplies* Taxes	5,148.00 19,782.82 0.00 50.00 1,622.50
				I	Estimate T	Total \$2	26,603.32
	* Shop Supply & Hazmat Fees: This charge represent	ts costs and profits (where applicable) to this r	epair facility fo	miscellaneo	us shop supplies, a	and/or waste remo	oval
Authorization	Original Estimate Total: 0.00 Authorization Method: email Date: Authorized By:	l text pl Contact Details:	hone	fa	ах	in persor	ı

All Quotes / Estimates valid for 30 days

Customer Signature

Χ \_\_\_\_\_